



1/26/99
meeting
conference call
w/ Kieth Watson
Debra

C. Hairey
Cottine Gibson
Bill Spedding
Peter Goetz
Scott Lockhent
Elena Tembreull
Relph Doslhopf




Issues To Be Discussed

• Issue 1: Storm Sewer Infiltration

• Issue 2: Seepage from North/West Bank of Williams Ditch

• Issue 3: Status of Stockpiles



Issue 1: Storm Sewer Infiltration

While installing the ditch bypass system, free product was observed flowing into the upstream limits of the sediment management area via the 36" storm sewer that services Arco Drive south of Williams Ditch.

The storm sewer systems servicing Arco Drive and Frenchmens Road were cleaned and videotaped.



Issue 1: Storm Sewer Infiltration

Based on the results of the videotaping activities, sections of both storm sewer systems were identified as potential avenues of infiltration.

As a result, three options were developed to address these sections.



Issue 1: Storm Sewer Infiltration

Options Considered

- Remove existing system and replace with RCP system
- Remove existing system and replace with HDPE system
- Use an in-situ method to prevent infiltration into these sections.



Toledo Tie Treatment Site Kerr-McGee Chemical, LLC

Time Critical Removal Plan

Scott Town term
Selection Sever Infiltration

be all shaped from Issue 1: Storm Sewer Infiltration

Amend and Sewer Infiltration

Reco-Recommended Option: In-situ method

bookfill with clay at put

and in handpipe to the system together


- Slipline the Arco Drive and half of the Frenchmens Road storm sewer systems.
- Replace the half of the Frenchmens Road storm sewer system that has already been removed with an HDPE system.




Issue 2: Seepage from North/West Bank

During the sediment removal process, seeps/pockets of product were observed on the north and west banks of Williams Ditch.

GENERAL SEEP LOCATIONS



GENERAL LOCATION OF SEEPS





SEEPS ALONG SOUTH SIDE OF LBA PARKING LOT






SEEPS ALONG EAST SIDE OF LBA





SEEPS AT FIRST 90 DEGREE BEND EAST OF ARCO







Issue 2: Seepage from North/West Bank

Initially, approximately six inches of soil were scraped off the banks in the area where seeps were observed. Although this removed the original seeps, some new seeps were exposed.



SEEP AREA AFTER SCRAPING






Issue 2: Seepage from North/West Bank

In order to investigate the location of the seep materials, a truck mounted Geoprobe® was used to collect soil borings within the LBA parking lot. Due to insufficient access, soil borings were not collected between the eastern side of the LBA building and the ditch bank.

APPROXIMATE SOIL BORING LOCATIONS




GENERAL LOCATION OF SEEPS



APPROXIMATE SOIL BORING LOCATION



SOIL BORING No. 4





Issue 2: Seepage from North/West Bank

Based on these soil borings, it was determined that the seeps/pockets of product extended into the LBA parking lot. As a result, options for addressing the seeps needed to be evaluated.



Issue 2: Seepage from North/West Bank

Options Considered

- Excavate and Remove Source Material
- Sheet Piling
- Line Ditch (FML, Clay, Concrete)
- Enclose Williams Ditch



how deep were test pits?

H'-not deep enough

manifold parking lot and root drawn

Toledo Tie Treatment Site Kerr-McGee Chemical, LLC Time Critical Removal Plan


Issue 2: Seepage from North/West Bank

Recommended Option: Enclose Williams Ditch

Enclose Williams Ditch with two 48" HDPE pipes from Arco Drive to the second 90 degree bend in Williams Ditch.



CONCEPTUAL DRAWING OF PIPE LAYOUT



■ GENERAL LOCATION OF SEEPS



APPROXIMATE SOIL BORING LOCATION





Issue 3: Status of Stockpiles

- Are the clean, questionable, asphalt, and subgrade piles a listed hazardous waste?
- Is there a ninety day storage issue?
- What determines if a contaminated media still contains a listed waste?

2500 formatarial state sind mangement per approval Issue 3: Status of Stockpiles

If there is a ninety day storage issue, request the thirty day storage extension.


Establish site specific, health-based screening levels to determine if the media still contains a listed waste

Obtain approval of the screening levels from U.S. EPA.

to remove to wasta according to wasta according to EPA approved then to go EPA approved then to go EPA approved the to the total according to the total accordin



Issue 3: Status of Stockpiles





Issue 3: Status of Stockpiles Does the contaminated media stockpile meet the definition of a characteristic hazardous waste as defined in 40 CFR 261? YES NO The stockpile is a characteristic The stockpile is not a hazardous waste, hazardous waste. but is it still a solid waste?

